Exhibit 1

12315	CN	Undated	Brochure (attached to claim form)	Toronto District School Board Brochure re: Roden Junior Public School - proof of construction date	100 Oak Street Hampton, SC	Speights & Runyan
12315	CN	3/26/03		Letter/Report from Pinchin Environmental to Toronto District School Board re: identification of fireproofing as MK-3	100 Oak Street Hampton, SC	Speights & Runyan
12315	CN	1981	Report	Sampling of Materials Suspected to Contain Asbestos Carried Out at Roden Junior Public School by Trevor Harris & Associates	100 Oak Street Hampton, SC	Speights & Runyan
12315	CN	1981	Report	The Toronto Board of Education - Roden Junior Public School - Asbestos Removal	100 Oak Street Hampton, SC	Speights & Runyan
12315	CN	8/19/91	Report	Bulk Sample Analysis by Pinchin & Associates - Lab Reference # b3272 - 1991	100 Oak Street Hampton, SC	Speights & Runyan
12315	CN	4/14/92	Report	Bulk Sample Analysis by Pinchin & Associates - Lab Reference # b3900 - 1992	100 Oak Street Hampton, SC	Speights & Runyan